SAFETY RECALL NOTICE

Bombardier Recreational Products Inc.
565 de la Montagne Street
Valcourt, Québec, Canada J0E 2L0
T 450.532.2211 F 450.532.5133

www.brp.com

Date: June 20, 2006

Dear Bombardier* ATV and Can-Am™ Owner,

This notice is sent to you in accordance with the requirements of the Consumer Product Safety Act, the Canada Motor Vehicle Safety Act and other applicable laws.

What is the reason for this notice?
In cooperation with Transport Canada and the U.S. Consumer Product Safety Commission, Bombardier Recreational Products Inc. and BRP US Inc. ("BRP") are conducting a voluntary safety recall of all 2006 and of some 2007 Outlander 650 and 800 ATV models. **Our records indicate that you are the owner of a potentially affected vehicle.**

What is the potential problem?
In some circumstances, some operators could ride with their foot slightly engaging the rear brake foot lever and not notice it due to the high performance of the engine. If this occurs, the rear brake may overheat because of its high efficiency and can ignite and in some situations lead to a vehicle fire of various intensities. This situation can potentially cause serious injuries or even death to riders or bystanders.

What should you do?
Being aware of this potential situation, you must be especially careful not to ride with the rear brake foot lever engaged. Moreover, BRP offers you a modification to your vehicle. Call an authorized BRP dealer/distributor and make an appointment to have your vehicle repaired. *This work will be performed at no charge to you.*

To contact your nearest authorized BRP dealer/distributor, visit www.can-am.brp.com, or contact us by phone at the number below.

What to do if you feel this notice is an error?
This notice was mailed to you according to the most current information we have available. If you no longer own this vehicle or some information in this notice is incorrect, please contact BRP at your earliest convenience.

If you have questions.
If you have questions about this notice, please call:
In the US and Canada: 1 (888) 864-2002, 8:00 to 18:00 eastern time.

We apologize for any inconvenience this may cause you. Thank you for your immediate attention to this matter.

Sincerely,
BRP After-Sales Service Department

Ski-Doo
Lynx
Sea-Doo
Evinrude
Johnson
Rotax
Can-Am

® Trademarks of Bombardier Recreational Products Inc. or its affiliates.
* Trademark of Bombardier Inc. used under license.