

SAFETY RECALL NOTICE

**Bombardier Recreational Products Inc.**

565 de la Montagne Street
Valcourt, Québec, Canada J0E 2L0
T 450.532.2211 F 450.532.5133

www.brp.com

Date: February 8, 2007

Dear Bombardier[†] ATV Owner,

This notice is sent to you in accordance with the requirements of the Consumer Product Safety Act, the Canada Motor Vehicle Safety Act and other applicable laws.

What is the reason for this notice?

WARN Industries Inc. informed Bombardier Recreational Products Inc. and BRP US Inc. ("BRP"), that the **WARN* winches** equipped with a **"8 post contactor"** installed on certain 2004 and 2005 XT Bombardier ATV models may be defective and that they were conducting a safety recall. **Our records indicate that you are the owner of a potentially affected vehicle.**

What is the potential problem?

BRP was informed by WARN that they received one confirmed report of an 8 post contactor failure that resulted in excessive heat within the contactor. Under rare circumstances, the contactor could potentially create a fire hazard. BRP is warning you that if this occurs, it could lead to severe injury or even death.

What should you do?

Immediately contact your authorized BRP dealer with your vehicle model and serial number to get the winch contactor replaced. The contactor availability will most likely be limited due to the sudden great demand from most ATV manufacturers; therefore you may experience delays going from a few weeks to months. You **must proceed immediately with one of these three options** to prevent excessive heat within the contactor:

- **Option 1:** Get the winch contactor replaced by an authorized BRP dealer.
- **Option 2:** If parts are not available, get the winch contactor disconnected by an authorized BRP dealer. Your dealer will re-contact you to update your winch kit as soon as replacement parts are available.
- **Option 3:** If you can not get the winch contactor immediately replaced or disconnected, or if you do not need to use your vehicle before parts are available, disconnect the vehicle battery as described in the vehicle Operator's Guide.

This work will be performed at no charge to you.

What to do if you feel this notice is an error?

This notice was mailed to you according to the most current information we have available. If you no longer own this vehicle or some information in this notice is incorrect, please contact BRP at your earliest convenience.

If you have questions about this notice or to find you're nearest authorized BRP dealer/distributor: Please visit www.can-am.brp.com or call in the US and Canada: 1 (888) 864-2002, 8:00 to 18:00 eastern time.

We apologize for any inconvenience this may cause you.
Thank you for your immediate attention to this matter.

Sincerely,
After Sales Service Department
Bombardier Recreational Products Inc.

Ski-Doo
Lynx
Sea-Doo
Evinrude
Johnson
Rotax
Can-Am

® Trademarks of Bombardier Recreational Products Inc. or its affiliates.

[†] Trademark of Bombardier Inc. used under license.

* Trademark of Warn Industries Inc.